

SUMMER 2018 - RESULTS FOR TESTING OF LEAD IN WATER LEVELS AT THIRTEEN APS SITES (SECOND BATCH IN THREE YEAR CYCLE)

			In Parts/Billion - PPB	
Collect Date	Site	Param	Method	Result
6/12/2018	Ashlawn Kitchen Sink	Lead	EPA 200.8	ND
6/12/2018	Ashlawn Fountain at 214	Lead	EPA 200.8	0.5
6/12/2018	Ashlawn Fountain at 229	Lead	EPA 200.8	ND
6/12/2018	Arlington Trad. Clinic Fountain	Lead	EPA 200.8	ND
6/12/2018	Arlington Trad. Fountain at 211	Lead	EPA 200.8	ND
6/12/2018	Arlington Trad. Kitchen Sink	Lead	EPA 200.8	0.3
6/13/2018	Carlin Springs Kitchen Sink	Lead	EPA 200.8	0.6
6/13/2018	Carlin Springs Gym Fountain	Lead	EPA 200.8	ND
6/13/2018	Carlin Springs Fountain at 216	Lead	EPA 200.8	ND
6/13/2018	Campbell Fountain at 133	Lead	EPA 200.8	ND
6/13/2018	Campbell Kitchen Sink	Lead	EPA 200.8	ND
6/13/2018	Campbell Bottle Filler at 131	Lead	EPA 200.8	ND
6/12/2018	Glebe Fountain C203	Lead	EPA 200.8	ND
6/12/2018	Glebe Clinic Fountain	Lead	EPA 200.8	ND
6/12/2018	Glebe Kitchen Sink	Lead	EPA 200.8	1
6/14/2018	Key Kitchen Sink	Lead	EPA 200.8	ND
6/14/2018	Key Gym Fountain	Lead	EPA 200.8	ND
6/14/2018	Key Fountain at 300	Lead	EPA 200.8	ND
6/13/2018	Long Branch Clinic	Lead	EPA 200.8	0.3
6/13/2018	Long Branch Cafetria Bottle Filler	Lead	EPA 200.8	ND
6/13/2018	Long Branch 2nd Floor Bottle Filler	Lead	EPA 200.8	ND
6/14/2018	McKinley Fountain by 343	Lead	EPA 200.8	ND
6/14/2018	McKinley Kitchen Sink	Lead	EPA 200.8	ND
6/14/2018	McKinley Gym Bottle Filler	Lead	EPA 200.8	ND
6/14/2018	Nottingham Café Bottle Filler	Lead	EPA 200.8	ND
6/14/2018	Nottingham Kitchen Sink	Lead	EPA 200.8	ND
6/14/2018	Nottingham Fountain at 173	Lead	EPA 200.8	ND
6/14/2018	Oakridge Bottle Filler at 217	Lead	EPA 200.8	ND
6/14/2018	Oakridge Kitchen Sink	Lead	EPA 200.8	ND
6/14/2018	Oakridge Café Bottle Filler	Lead	EPA 200.8	ND
6/13/2018	Patrick Henry Kitchen Sink	Lead	EPA 200.8	0.3
6/13/2018	Patrick Henry Gym Fountain	Lead	EPA 200.8	ND
6/13/2018	Patrick Henry Bottle Filler at 185	Lead	EPA 200.8	ND
6/14/2018	Swanson Gym Bottle Filler	Lead	EPA 200.8	ND
6/14/2018	Swanson Kitchen Sink	Lead	EPA 200.8	0.2
6/14/2018	Swanson Fountain at 202	Lead	EPA 200.8	ND
6/14/2018	Williamsburg Bottle Filler Office	Lead	EPA 200.8	ND
6/14/2018	Williamsburg Kitchen Sink	Lead	EPA 200.8	0.5
6/14/2018	Williamsburg Bottle Filler Gym	Lead	EPA 200.8	ND

NB: Most were none detected and none are even close to actionable level - 15 PPB

Any questions on these results can be directed to Jim Meikle, Director of
Maintenance APS - 703 228 6617