

JAMESTOWN ELEMENTARY SCHOOL - TESTING OF LEAD IN WATER & REMEDIATION (July-Oct 2016)

Area/Room	Draw 1		Flush 2		Area/Room	Draw 1		Flush 2		Area/Room	Draw 1		Flush 2				
	PPB	PPB	Rev	PPB		PPB	PPB	Rev	PPB		PPB	Rev	PPB	PPB	Rev	PPB	
811	1.1	<1			506	2.5	2.1			702	ND	ND			200	1.1	<1
804 Kitchen	1.6	<1			506A	1.7	<1			704	2	2			110	3.3	<1
800 Cafeteria Fountain High	41.8	37.2	Eliminated		508	<1	<1			706 Sink 1	<1	<1			at 110 Water Fountain	1.1	<1
800 Cafeteria Fountain Low at 416 Hall Fountain R	16.8	9	Eliminated		512	3.8	<1			706 Sink 2	<1	<1			111	60.6	2.4
at 416 Hall Fountain L	<1	<1			at 522 Hall Fountain L	<1	<1			701	<1	<1			112	9.3	1.6
418	<1	<1			at 522 Hall Fountain R	<1	<1			at 702 Hall Fountain R	<1	<1			108A	1.5	<1
415	1.7	<1			520	<1	<1			at 702 Hall Fountain L	<1	<1			108	<1	<1
406	1.4	<1			521	<1	<1			711	1	<1			106A	<1	<1
404	398	2.7	11		513	2.5	<1			710	3.2	<1			105	3.6	<1
402	83.3	1.4	12		515	1.1	<1			712	1.7	<1			106	2.1	2.1
401	53.9	1.2	14	515A	3	1.9				713	1.9	<1			107	4.1	<1
403	26.3	1.2	4	607	1.3	<1				804	4.5	1.9			115	<1	<1
405	386	1.3	2	607A	17.3	1.7	2	809		809	4.2	1.2			116	<1	<1
407	62.3	8	3	608	3.3	1.1		809A		809A	6.2	<1			Kitchen	<1	<1
411	15	1.2	6	608A	8.4	1.1								417	1.8	<1	
413	5.1	ND	4	605	12	1								415 Sink 2	1.2	<1	
412	20.2	4.4	14	605A	3.7	<1		810		810	1	<1		415 Sink 3	1.2	<1	
410	46.7	ND	8	606	2.9	<1		at 800 Hall Fountain		at 800 Hall Fountain	<1	<1		416	<1	<1	
414	20.9	ND		606A	21.6	2.3	2	300		300	<1	<1		414 Sink 1	<1	<1	
501	ND	1		at 605 Hall Fountain	<1	2.8		207		207	<1	<1		414 Sink 2	2.6	1.8	
503	ND	ND		603	8.1	2.7		205 Sink 1		205 Sink 1	1.9	<1		522	<1		
503A	3.1	2.8		603A	14.6	2.2	3	205 Sink 2		205 Sink 2	<1	<1					
505	1.1	<1		604	5.2	1.1		205 Sink 3		205 Sink 3	2.7	2.1					
505A	<1	<1		604A	14.3	2.7	2	205 Sink 4		205 Sink 4	<1	<1					
507	<1	<1		601	2.9	1		at 305 Hall Fountain		at 305 Hall Fountain	<1	<1					
507A	<1	<1		601A	8.8	ND		206		206	<1	<1					
509	1.5	<1		602	ND	5.7		204 Sink 1		204 Sink 1	1.2	<1					
509A	1.6	<1		602A	22.8	2.1	2	204 Sink 2		204 Sink 2	2.1	<1					
511	1.4	<1		at 601 Hall Fountain	ND	ND		204 Sink 3		204 Sink 3	1.5	<1					
511A	1.1	<1						204 Sink 4		204 Sink 4	1.5	1.9					

Notes:
 1 'Draw' is taken immediately device is turned on
 2 'Flush' is taken after device runs for thirty seconds

ND Equals NON DETECTED (no lead content)
 PPB Equals Parts Per Billion (lead content)
 15.0 + Equals remediation action required

